


MODEL DM10 3½ DIGIT NEMA 4X LOOP-POWERED METER



- 1 V Drop
- 1" High Display
- Operates From -40 to 185°F

ACTUAL SIZE

SPECIFICATIONS

Except where noted all specifications apply to operation at 77°F (25°C).

ENCLOSURE: Impact-resistant plastic; body: gray ABS; cover: clear polycarbonate. NEMA Type 4X, IP 66/67 (EN60529)

DISPLAY: 1.0" (25.4 mm) high LCD, -1000 to 1999

INPUT: 4-20 mA

CALIBRATION: Two-step; non-interacting low and high

CALIBRATION RANGE: 4 mA input: -1000 to +1000; 20 mA between 20 and 2000 counts > 4 mA display (up to 1999)

ACCURACY: ±0.1% of span ±1 count

CONVERSION RATE: 2.5 conversions/second

MAXIMUM INPUT CURRENT: 30 mADC

MAXIMUM VOLTAGE DROP: 1 V at 20 mA

CONNECTIONS: Screw terminal block

OPERATING TEMPERATURE RANGE: -40 to 185°F (-40 to 85°C)

WARRANTY: 1 year parts and labor

DISCLAIMER: The information contained in this document is subject to change without notice. Fluid Components International LLC makes no representations or warranties with respect to the contents hereof, and specifically disclaims any implied warranties of merchantability or fitness for a particular purpose.

ORDERING INFORMATION

| Model | Description | ½" Conduit Hole Location |
|--------|-----------------------------|--------------------------|
| DM10 | 3½ Digit Loop-Powered Meter | Bottom |
| DM10-R | 3½ Digit Loop-Powered Meter | Rear |
| DM10-T | 3½ Digit Loop-Powered Meter | Top |
| DM10-N | 3½ Digit Loop-Powered Meter | None |

ACCESSORIES

| Model | Description |
|-----------|--|
| DM10-KIT1 | Panel Mount Kit (does not provide NEMA 4X seal to panel) |
| DM10-KIT2 | 2" Pipe Mounting Kit (zinc plated steel) |
| DM10-KIT3 | 2" Pipe Mounting Kit (stainless steel) |

YOUR LOCAL DISTRIBUTOR IS:

MODEL DM10 3½ DIGIT NEMA 4X LOOP-POWERED METER

Calibrator Connected to Input Signal PCB




Figure 1

Control loop Connected to Input Signal PCB




Figure 2

Field wiring is made to the Input Signal PCB which is mounted to the base of the enclosure.

Calibrator Connected to Display PCB




Figure 3

The Display PCB may be removed from the enclosure for bench calibration. Loop Jumper must be installed on Input Signal PCB to maintain loop, refer to procedures below.

Protect enclosure from exposure to chemical solvents and excessive ultraviolet (UV) light (e.g. sunlight).

NOTE: To prevent damage to electronic components caused by electrostatic discharge, a grounding strap should be worn when servicing the display.

Conduit Installation Instructions

1. Remove the Display PCB from the enclosure
2. Connect ½" conduit fittings to the hole in the enclosure
3. Connect conduit (with attached hubs*) to the enclosure

* Use only conduit hubs that are designed to maintain NEMA 4X or IP ratings.

Note: Please read DM10 Intrinsic Safety Barrier Connections for more information pertaining to conduit holes.

Mounting Instructions

1. Remove the enclosure cover from the base.
2. Insert mounting hardware into mounting holes in enclosure base (see Figure 4).
3. Secure the enclosure base to the mounting surface using the inserted hardware.
4. Re-attach the enclosure cover to the base.

SETUP

Only a calibrated current source and a screwdriver are needed for calibration.

Calibration Connections

To access the input terminals it is necessary to remove the enclosure cover and the Display PCB. This is done by loosening the four screws on the enclosure cover and removing the cover. Completely loosen the left screw that holds the Display PCB to the enclosure and loosen the right screw about four turns so the Display PCB remains attached to the enclosure. Rotate the Display PCB 90° to gain access to the Input Signal PCB. Next, connect a calibrated current source as illustrated in Figure 1.

Decimal Point Selection

The decimal point jumper array is located in the lower right corner of the Display PCB next to the display. It is labeled DP1, DP2, DP3. Place a jumper over both pins of DP1 for a display of 199.9, DP2 for 19.99, or DP3 for 1.999.

Calibration

LO and HI calibration controls are located to the left of the display (see Figure 1). Apply a signal equal to 4 mA and adjust the LO control to display the desired reading. Apply a signal between 16 and 20 mA and adjust the HI control to display the desired reading. Complete the calibration procedure by making any minor adjustments to the LO and HI controls.

Installation

Installation of the meter involves removing the Display PCB from its enclosure and connecting a conduit fitting. Use conduit and fittings (not included) suitable for the degree of ingress protection required. Mounting holes are located at each corner of the enclosure. Refer to Figure 4.

Loop Connections

Disconnect power to the loop and install the meter as illustrated in Figure 2. Replace the enclosure cover.

Removing Display PCB From the Loop

The Display PCB and Input Signal PCB are connected together with one black and one red wire. The wires are soldered to the Display PCB and connected to a screw terminal connector on the Input Signal PCB.

To remove Display PCB:

1. Loosen the four screws on the enclosure cover and remove the cover from the enclosure base.
2. Completely loosen the left-side screw holding the Display PCB to the enclosure. Loosen the right-side screw four turns so the Display PCB remains secure to the enclosure.
3. Rotate the Display PCB 90° to gain access to the Input Signal PCB.
4. Install Loop Jumper over both pins to bypass Display PCB and allow the signal to flow through the Loop Jumper. The display will go off when the jumper is installed.
5. Disconnect the black and red signal wires from the screw terminal connector.
6. Loosen completely the right-side screw and lift Display PCB from the enclosure. Care should be taken to prevent static electricity from damaging the electronic circuitry.
7. Restore enclosure cover to the base to prevent contamination of components.

Restoring Display PCB to the Loop

1. Remove enclosure cover as described in step 1 in the preceding section.
2. Secure Display PCB to enclosure using right-side screw; do not tighten screw to allow rotation of Display PCB while accessing Input Signal PCB.
3. Connect red wire to S+ terminal and black wire to S- terminal, as shown in Figure 1.
4. Remove Loop Jumper to allow the signal to flow through Display PCB (save push-on jumper by placing over one pin only).
5. Tighten screws holding Display PCB and install enclosure cover.

Servicing Display PCB Outside the Loop

Two modes of input signal allow the user to remove the Display PCB for service without interrupting the loop as indicated above and operate the Display PCB at another location. The loop remains connected to the Input Signal PCB while the Display PCB is absent for service. The user may operate the Display PCB at another location by connecting a signal to the S+ and S- wires on the Display PCB as illustrated in Figure 3.




Figure 4

Dimensions and Mounting Information

| | | |
|-----------------------|-------------------|------------------|
| A: 3.15" (80 mm) | C: 2.36" (60 mm) | E: 2.56" (65 mm) |
| B: 5.51" (140 mm) | D: 4.72" (120 mm) | F: 0.79" (20 mm) |
| Weight: 12 oz (340 g) | | |

LIM685FC Rev A 09/04

FLUID COMPONENTS INTERNATIONAL LLC

USA: 1755 La Costa Meadows Drive • San Marcos CA • 92078 Phone: (800) 854-1993 • Fax: (760) 736-6250

Europe: Persephonestraat • 3-01 5047 TT Tilburg • The Netherlands • 31-13-5159989 • Fax: 31-13-5799036

FCT FLUID COMPONENTS
INTERNATIONAL LLC
www.fluidcomponents.com